



Workforce Management Solutions

Securing your time and resources

What's New – V2.17.07.1
Configuration Tool

This document is a listing of the changes made to the Configuration Tool. Please take careful notice of the items highlighted in yellow.

IMPORTANT:

As of 2017-09-07, configuration tool V2.17.07.1 is the only tool to be used.

2.17.07.1

- Fix IPB_R7 slave reader reset and set.

2.17.07.0

- Change script to not log printf to SD Card for EC3 and EABR

V2.17.04.0

- Added new IPB7 unit

V2.16.06.0

- Fix add controller out of range error

V2.16.05.0

- Fix IPB6 install error
- Fix wifi and gsm image.png copy

V2.16.04.0

- Install EC3/EABR with or without bin2 file


V2.16.01.0

This is the only configuration tool that must be used as of release on 2016-01-04.

- Fix the IPB reset app to start ipb7_v2.ko and not v1

V2.15.11.0

- Add in new kernel install for IPB7 (.ko file). Ensure that the .ko file is in the firmware folder when installing IPB7 reader firmware.
- Add valid IP address check (yellow)



V2.15.07.2

- EC3 WIFI configuration.
- New IPB controller | reader install for controller firmware V7.05 or higher and reader firmware V2.06 or higher.
- Touch screen plugin to install on EABR and ec3Config



V2.15.07.1

Add IPB multithread for IPB6

- The IPB6 unit type was not included in the multithread configuration

Force selection of both bin files before enabling upload

- The install button is not enabled until both bin files are selected in the case of multithread firmware.



V2.15.07.0

IPB reset application code

This is the only config tool to be used which any firmware V7.00 and above

V2.15.04.2

Impro Bio – EABR functionality

V2.15.04.1

Add in reader list sort and fix set and reset of reader

V2.15.04.0

Fix IPB install to upgrade and downgrade firmware between multithread and standalone

Remove unnecessary DB files when changing between multithread and standalone

Fix reader tab to show correct ID in list box

Add EABR install (Impro Bio)

V2.15.03.5

Change service scripts for EC3

V2.15.03.4

Fix EC3 install problem

V2.15.03.3

Added graphics for EC3 with screen

Add in reboot after installing EC3 service

V2.15.03.2

Added functionality to configure EC3 with display

V2.15.03.1

Add fix for EC3 service

V2.15.03.0

Added functionality to configure new EC3

V2.15.01.1

Added functionality for IPB7 multithread

V2.15.01.0

Fix IP mask display bug

V2.14.12.0

New Look

V1.2014.9.0

Continued with SLA expansion functionality

V1.2014.8.1

Add fix for config tool getting stuck

V1.2014.8.0

Add in new SLA functionality

V1.2014.5.1

Clear bin file in FWInstaller if device changes

Compatible with older versions of firmware

Lock Config screen if FWInstaller screen or Graphics Installer screen open

Fix error message writing